



## USB to Printer Adaptor

Model No. : UP101



### Overview

The USB-Parallel cable allows your PC to Print to any parallel printer device connected through the USB port. Just plug the USB connector of the cable into the USB port of your PC and the other end into the centronics connector of the parallel printer. USB (Universal Serial Bus) interface provides up to 12Mbps data throughput, so printing is much faster compared when connected to standard parallel port. The USB - arallel cable also provides true plug-n-plug and hot-plug capability- simple plug in the cable UNDER THE windows operating system and the cable will be instantly detected.

### Features

- Single chip (ASIC)USB to Parallel host to host communication
- Windows 98 and NT5.0 Driver Support
- Universal Serial Bus Specification Rev.1.1. compliant.
- USB full speed communication and bus powered.
- USB Printer Class Specification 1.0 compliant.
- IEEE-1284 1994 (bi-directional parallel interface) specification compliant.

### Specifications

Dimensions (LXWXH)	63 x 62 x 20mm
Unit Weight	150g
Cable Length	1.8M
Connect Ports	Printer
IEEE-1284 Printer port (DB-25)	X 1
Compliant with USB version	USB 1.0/USB 1.1
Power	By host bus power
OS Complies	Windows 98/98SE/ME/2000/XP